

M3 SONAR[®] QUICK START

1 INSTALL THE SOFTWARE

- a. Download the M3 software onto your computer from:
km.kongsberg.com/mesotechsoftware
- b. Run the Setup file.
- c. Apply the default settings during installation.
- d. Click **Yes** to install the KML USB Converter when prompted.



Power Supply




Ethernet Cable

M3 Sonar Cable

3 INSTALL YOUR SONAR

- a. Connect the M3 Sonar system units as shown.
- b. Plug in the Power Supply.



2 SET YOUR IP ADDRESS

- a. In Windows, open **Settings**.
- b. Select **Network & Internet**, then **Change adapter options**.
- c. Right-click on your Ethernet network and select **Properties**.
- d. Select **Internet Protocol v4**, then select **Properties**.
- e. Set your IP address to 192.168.1.233.
- f. Set the Subnet Mask to 255.255.255.0.



Kongsberg Mesotech Ltd.
Tel: (604) 464 8144

To download the M3 Sonar software or manuals, visit:

kongsberg.com/mesotechsoftware
kongsberg.com/mesotechdocumentation





KONGSBERG

M3 SONAR® QUICK START

4 DISCOVER YOUR SONAR

- Double-click the M3 Sonar icon on your desktop.
- Click **Setup** → **System Configuration** → **Devices** → **Sonar Setup**.
- Click the **Discover Sonar Heads** button.
- Select your Sonar Head.
- Click **Use Discovered Head**.
- Click **Close**.



5 RUN YOUR SONAR

- Click **Setup** → **Connect**.
- Verify that the sonar view updates.
- Verify that no errors appear in the **Output Messages** window.
- Click on "Active" on the right side of the status bar.
- Verify that all items listed under the M3 Sonar show green check boxes.

6 POWER OFF THE SONAR

- Click **Setup** → **Disconnect** in the M3 Sonar software.
- Close the M3 Sonar Software.
- Turn off the computer.
- Disconnect the power cord leading to the power supply, or switch off the breaker supplying power to the M3 Sonar.

